



Doufit EM-01/02 Elliptical Machine Screw Accessories (A)


For Assembly Step 1 - 4



M8 Acorn Nut (82) x 4
Step 1





M8*65mm Carriage Bolt (73) x 4
Step 1




M8 Curved Washer (65) x 10
Step 1/8/9


Plate Wrench(97)




M8*16mm Socket Cap Bolt(78) x 4
Step 3




M8 Washer(93) x 4
Step 3




M8 Split Washer(86) x 10
Step 3/5/8




M4*16mm Self Tapping Screw(19) x 2
Step 4



M6 Allen Wrench(95)
M8 Allen Wrench(96)




Multifunctional Wrench(98)




280L*200W

Doufit 01/02 Elliptical Machine Screw Accessories (B)


For Assembly Step 5 - 9




Pivot Wave Washer (57) x 2
Step 5




M8 x 20mm Hex Bolt (77) x 2
Step 5




Pivot Washer (67) x 2
Step 5




M16 Wave Washer (88) x 2
Step 6




Left M12 x 110mm Allen Bolt (91) & Left M12 Screw Nut (92)
Step 6




M13 Washer (89) x 2
Step 6




M8 x 16mm Allen Bolt (74) x 6
Step 8/9




Right M12 x 110mm Allen Bolt (87) & Right M12 Screw Nut (90)
Step 6




M10 Washer (72) x 4
Step 7



M10 Screw Nut (83) x 4
Step 7



M10 x 45mm Hex Bolt (76) x 4
Step 7



Grease Packet